3 July 1963

	STATINTL
Reference the adjustment work done July 2 - 3, it is the consensus that the equipment was placed in as good a condition as possible at the time. Voltage drops and possible minor mechanical mal- adjustments existing at the time did not make it possible to give final overall clearance of the quality of the operation of the components. Therefore has been released as having performed a work that could reasonably requested of him at the time. This how is not to be construed as a final acceptance of the equipment. The final acceptance cannot be made until the mechanical and line volt factors have been eliminated. This will be accomplished as soon a pessible after which further checks will be made on the performance of your components.	STATINTL STATINTL Sever dis
co:	STATINTL

Declass Review by NIMA/DOD